Grimm Audio MU2 firmware change log

v0.9.6

Bug fixes
1. Fixed issue introduced with Roon build 1365 that one could not log into Roon after a database reset.

Improvements
1. Default startup volume changed to -42dB.
2. Display of the MU1 will show "Roon Server Disabled" if the server was stopped via the GRUI.
3. Update system improvements.

New Features
1. Added fixed volume option.
2. Jump to source Roon when pressing play in the Roon app if source was not Roon already.
3. Added self test for system integrity.

v0.9.3

Improvements
1. Auto mount music disk in Roon.

Bug fixes
1. Fixed Roon start and stop buttons in GRUI.
2. Various underwater fixes.

https://www.grimmaudio.com