



Grimm Audio MU1 firmware change log

v1.1.2

Bugfixes

1. Jumping volume bug fixed
2. Irregular audio mute and power led blinking bug fixed.

v1.1

New features

1. DXD support.
2. DSD128 support.
3. DSD256 support.
4. Stand-by functional.
5. Volume control on digital output 2.
6. Support mode added.
7. Roon database and logs available through the network (more information in the manual).
8. Mute during clock switch.
9. Current and to be installed software version will be shown in the update menu [4/5].

Improvements

1. Major Roon Extension improvements, it is stable with multiple endpoints now. (Requires re-enabling the extension).
2. Display renderer improvements.
3. Power LED brightness reduced.
4. Internal control software upgrade.
5. Display refresh rate upgrade.
6. Shutdown animation added.
7. Internal update improvements.

Bugfixes

1. Playback speed bug after offering 176.4/192kHz sample rates on digital input fixed.
2. USB mounter fixed: USB devices do not need to be unplugged and re-plugged after reboot anymore.
3. MU1 to second MU1 playback fixed when more than 1 MU1 is present in the network.
4. Date & time bug fixed. Caused Qobuz to sometimes fail playback.
5. User setting bug fixed.

<https://www.grimmaudio.com>